GEOKINETICS INC. shale oil development and production
391 Chipeta Way D-2

• Salt Lake City, Utah 84108-1282

file ACT/04.7/6 C.C. J. Whitehend P. Gruhaish-li

Telephone (801) 583-0511

November 10, 1986

Mr. John J. Whitehead State of Utah Division of Oil Gas & Mining 355 W. North Temple 3 Triad Center, Suite 350 Salt Lake City, UT 84180-1203

RE: Reclamation & Revised Bonding, Geokinetics Inc. Seep Ridge Project, ACT/047/002, Uintah County, Utah.

Dear John:

Thank you for your letter of October 20, 1986. Since the visit to Kamp by Pam and Kathy, we have finalized plans for the suspension of operations. Certain items that we had planned to remove will be retained, and others that we had planned to retain have been removed.

The changes to the list of items to be in suspension, dated September 26, 1986, are as follows:

- A. Additions
  - 1. Afterburner
  - 2. Absorber Tower
  - 3. 3000 bbl tanks (2)
  - 4. Modular office building
  - 5. Mobile homes (10)
  - 6. Equipment stacked on site
  - 7. Final site cleanup
- B. Deletions
  - 1. Power lines
  - 2. Pond #3 backfill
  - Pond #3 revegetate 3 acres

We would be happy to have your people come to the site and estimate the cost of the additional items.


Sincerely,

GEOKINETICS INC.

Mike

Mitchell A. Lekas President

MAL/ph



DIVISIUN UF OIL, GAS & MINING

## CHANGE IN FILE STATUS APPROVAL FORM

DATE November 4, 1986

CURRENT FILE NO. ACT/047/019

RECOMMENDED FILE NO. ACT/047/002 and INA/047/019

COMPANY AND MINE NAME Seep Ridge Oil Company - Seep Ridge Project

## REASON FOR CHANGE IN FILE STATUS

Both ACT/047/019 and ACT/047/002 are on the same site and the same company. ACT/047/019 should be combined with ACT/047/002 and the File No. ACT/047/019 retired.

of return to INA 047/019

of return to INA 047/019

we should get states of this and other Toxtopocult

or field check of this and 1872 is

preparties in a field cleck in

preparties in a field cleck in

REQUESTORS NAME Frank Filas, Engineer	
REQUESTORS SIGNATURE	
ADMINISTRATOR'S NAME Lowell Braxton	
ADMINISTRATOR SIGNATURE	
0943R-10	